

State of Utah

Department of **Natural Resources**

MICHAEL R. STYLER Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA Division Director Representatives Present During the Inspection: Vicky S. Miller Environmental Specialist Steve Demczak Environmental Scientist III

Inspection Report

Permit Number:	C0070039
Inspection Type:	COMPLETE
Inspection Date:	Thursday, November 12, 2009
Start Date/Time:	11/12/2009 10:00:00 AM
End Date/Time:	11/12/2009 2:00:00 PM
Last Inspection:	Wednesday, October 07, 2009

Inspector: Steve Demczak, Environmental Scientist III

Weather: Sunny, 50's

InspectionID Report Number: 2200

Accepted by: jhelfric 12/7/2009

Permitee: CANYON FUEL COMPANY LLC Operator: CANYON FUEL COMPANY LLC

Site: **DUGOUT CANYON MINE**

Address: PO BOX 1029, WELLINGTON UT 84542

County: CARBON

JON M. HUNTSMAN, JR. Governor GARY R. HERBERT Lieutenant Governor

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current Acreages

Total Permitted	9,751.00
Total Disturbed	104.70
Phase I	
Phase II	
Phase III	

Mineral Ownership **✓** Federal

V State

Types of Operations ✓ Underground Surface

	- Late	 our lace
	County	Loadout
✓	Fee	Processing
	Other	Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

There are no pending compliance actions for the Dugout Canyon Mine permit area.

The Permittee is current relative to the required electronic quarterly water monitoring submittals for 2009.

Inspector's Signature:

Steve Demczak, Environmental Scientist III

Date

Thursday, November 19, 2009

Inspector ID Number: 39

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

, Permit Number: C0070039 Inspection Type: COMPLETE

Inspection Date: Thursday, November 12, 2009

Page 2 of 4

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- Substantiate the elements on this inspection by checking the appropriate performance standard.
 For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	✓		✓	
2.	Signs and Markers	V		~	
3.	Topsoil	✓		✓	
4.a	Hydrologic Balance: Diversions	✓		✓	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	✓		✓	
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring	✓		✓	
4.e	Hydrologic Balance: Effluent Limitations	✓			
5.	Explosives	✓			
6.	Disposal of Excess Spoil, Fills, Benches		V		
7.	Coal Mine Waste, Refuse Piles, Impoundments	✓		V	
8.	Noncoal Waste	✓		✓	
9.	Protection of Fish, Wildlife and Related Environmental Issues	V			
10.	Slides and Other Damage	✓		✓	
11.	Contemporaneous Reclamation		V		
12.	Backfilling And Grading		V		
13.	Revegetation		V		
14.	Subsidence Control	V		✓	
15.	Cessation of Operations		✓		
16.a	Roads: Construction, Maintenance, Surfacing	~			
16.b	Roads: Drainage Controls	✓		✓	
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations	✓		V	
19.	AVS Check	✓			
20.	Air Quality Permit	✓			
21.	Bonding and Insurance	✓		V	
22.	Other				

Permit Number: C0070039
Inspection Type: COMPLETE

Inspection Date: Thursday, November 12, 2009

Page 3 of 4

1. Permits, Change, Transfer, Renewal, Sale

DOGM Permit will expire on March 17, 2013. Air Quality permit number is DAQUE-AN0116340009-07. UPDES permit number is UT0025593 and expire on Nov. 30, 2009. The SPCC Plan was refviewed on March 14, 2008.

2. Signs and Markers

The permit sign is located at the gate to the property. Information meets the minimium requirements of the R645 Coal Rules.

3. Topsoil

The topsoil pile next to the refuse pile were inspected. There is some vegetated growth which includes some weeds. There were no signs of wind or water erosion to the piles.

4.a Hydrologic Balance: Diversions

The diversions were spot inspected and were functioning as designed.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

I inspected the sediment pond; and it did contain water but was not discharging during the inspection. The pond was cleaned out a few of months ago. No hazardous conditions were noticed during the inspection. The sediment pond was inspected on June 30, 2009 by the permittee.

4.d Hydrologic Balance: Water Monitoring

The permittee has sent the second quarter water data to the Division.

7. Coal Mine Waste, Refuse Piles, Impoundments

The waste rock site was inspected with no hazardous conditions noticed during the inspection. The permittee inspected the refuse pil;e on Aug 12, 2009. This was conducted by a P.E.. No hazardous conditions were reported.

8. Noncoal Waste

The mine site was clear of non-coal waste materials.

10. Slides and Other Damage

No slides or other damage was noticed during the inspection.

14. Subsidence Control

This information is in the annual report.

16.b Roads: Drainage Controls

Road diversions were inspected and were functioning as designed.

Inspection Continuation Sheet

Permit Number: C0070039 Înspection Type: COMPLETE

Inspection Date: Thursday, November 12, 2009

Page 4 of 4

18. Support Facilities, Utility Installations

No new facilities constructed since the last inspection.

21. Bonding and Insurance

The insurance policy will expire on July 31, 2010. The accord form was reviewed and meets the requirements of the R645 Coal Rules. The bonding amount is \$3,550,000. The Reclamation Agreement was inspected and is signed by the Division. The total disturb area is 104.70 acres.